50

COMPLETION REPORT

1	Name of the work	Repairs of culverts in ward no. 13 shettyhalli sub division.
2	Sanctioned Estimate No. & Date	EE/DD/TS/78/16-17 dated 10/01/17
3	Head of Account which is chargeable	D-code 1771
4	Instrument Order NO. & Date	EE/DD/WO/69/17-18 dated 11/05/17
5	Name Of Contractor	Sri. N. Shivananda, No. 35, 2nd cross, 1st A Main road, Defiance colony, Bagalagunte, Bangalore.
6 a	Time Stipulated for Completion of work	90 days
b	Delay in Exculpation of Work	—
7	Measurement recorded in	MB NO 581/17-18 page NO 58011 to 58017/2
8	Check Measurement of the Asst	MB NO 581/17-8 page NO 58011 to 58017/2
9	Name of the office/official in charge of the work	AEE (SSD)
10	a) Asst. Eng/junior Eng	ಯು ಎಂ ಡಿ
	b) Asst. Exe Engineer	ಡಿ ಜೆ ಎಂ ಇ

Sanctioned Estimate Amout	Amout Claims As per Actually Vide As per bills	Excess	Savings
	1783546-80	—	16369-00

1) Certified that the above work has been completed within the stipulated time noted in the
2) Certified that the contractor has delayed and completed the work for which necessary fine recovered
3) Certified that the above work has been executed by the contractor satisfactory in

ASSISTANT ENGINEER.

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike,
Dasarahalli Division, Bangalore-57

ASSIATANT EXECUTIVE ENGINEER
ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾ
ಬೆಂಗಳೂರು-೫೭. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂ